: FLOAT SKIDTUBE

: D412742013

N/A

: N/A

: N/A

: 12/30/2007

Date:

Wednesday, 12/5/2007 12:56:51 PM

User

Kim Johnston

**Process Sheet** 

**Drawing Name** 

**Part Number** 

Material

**Due Date** 

**Drawing Number** 

Project Number

**Drawing Revision** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 35741

S.O. No. :

**Estimate Number** 

: 10366

P.O. Number

: 12/5/2007

This Issue

Prsht Rev.

: NC

: // First Issue : 35740

Previous Run

Written By

Checked & Approved By

Comment

05.10.13 Est Rev:B

Est RevC

Type

06-06-08

07-12-03

ECN 1072

: LANDING GEAR

KJ/JLM New Issue As per DSI9336 JLM

DD verified by:JLM

Qty:

Each

1 Um:

K3 0712.06

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description: DOCUMENT CONTROL

1.0

DC

Comment: DOCUMENT CONTROL

Photocopy bluefile and create labels per PPP D412-742-013

CHG003 00

2.0

3.0

35741A

FLOAT SKID ASSEMBLY



D412-742-043 B

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

4.0

D2571

Saddle, Fwd, Out



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

**Qty Part Number** 

1 D2571

Description

Saddle Fwd Outside



5.0

D2572

Comment: Qty.:

1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

**Qty Part Number** 

1 D2572

Description

Saddle Fwd Inside

Batch

W/O:			WC	ORK ORDER CHANG	GES				
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·					
Part No	):	PAR #:	Fault Cate	jory:	NCR: Yes	s No DC	QA:	Date: _	<del></del>
					QA:	N/C Close	ed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NO	R)			
DATE	STEP	Description of NC		tion B	Verif	ication	Approval	Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat	Sec	tion C	Chief Eng	QC Inspector
•						the state of the s			
1									

Wednesday, 12/5/2007 12:56:51 PM Date: Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 35741 Part Number: D412742013 Job Number: Description: Seq. #: **Machine Or Operation:** Saddle, Aft, Out 6.0 D2573 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Batch Description Saddle Aft Outside 1 D2573 D2574 NewBatch 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Saddle Aft Outside 1 D2574 D2876 8.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D2876 Saddle Spacer 9.0 D2877 Saddle Spacer Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description B34818 2 D2877 Saddle Spacer 10.0 D34031 Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Description Qty Part Number Batch 16 D3403-1 Bushing 08/03/19 11.0 D2747 Set Screw Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: **Qty Part Number** Description 4 D2747 Bolt

	Dart	Aeros	pace	Ltd
--	------	-------	------	-----

Dait Ac	Ospaci	5 Ltd							
W/O:			WC	RK ORDER CHANG	ES				······
DATE	STEP	PROC	EDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:					
					QA: N	/C Close	d:	_ Date: _	
NCR:		We	ORK ORDE	R NON-CONFORMA	ANCE (NCR	(1)			
DATE STE		Description of NC			on B	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector
	<u> </u>								
		N/							

Wednesday, 12/5/2007 12:56:51 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 35741 Part Number: D412742013 Job Number: Description: Seq. #: Machine Or Operation: 12.0 D35331 Set Screw Comment: Qty.: 2.0000 Each(s) Total: Set Screw 28093 AN4C6A 13.0 Comment: Qty.: 16,0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Description Qty Part Number 16 AN4C6A Bolt AN4C52A 14.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description Batch 8 AN4C52A Bolt AN6C12A 15.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description Batch M104289 8 AN6C12A Bolt D36723 PHENOLIC WASHER 16.0 Comment: Qty.: 32.0000 Each(s)/Unit Total: 32-0000 Each(s) PHENOLIC WASHER AN960C416L Comment: Qty.: 32.0000 Each(s)/Unit Total: 32.0000 Each(s) **WASHER** 18.0 D36729 Comment: Qty.: Total: 8.0000 Each(s) 8.0000 Each(s)/Unit PHENOLIC WASHER

Dart A	\erosi	pace	Ltd
--------	--------	------	-----


	•									
W/O:			W	ORK ORDER CHANG	GES			W		
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				<i>;</i>						
· · · · · · · · · · · · · · · · · · ·										
							•			
Part No	·	PAR #:	Fault Cate	gory:	_ NCR:	Yes I	lo <b>DQ</b>	<b>A</b> :	_ Date: _	
						QA: N/	C Close	d:	_ Date: _	
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC			tion B		Verific	cation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	on C	Chief Eng	QC Inspector

Wednesday, 12/5/2007 12:56:51 PM Date: Kim Johnston User: **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: FLOAT SKIDTUBE Job Number: 35741 Part Number: D412742013 Job Number: Seq. #: Machine Or Operation: Description: WASHER 19.0 AN960C616L 8.0000 Each(s)/Unit 8.0000 Each(s) Comment: Qty.: Total: 8918 WASHER D367211 HENOLIC WASHER 20.0 Comment: Qtv.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) PHENOLIC WASHER MS210434 24.0000 Each(s) Total: Comment: Qtv.: 24.0000 Each(s)/Unit 08/03/ Nut 22.0 AN4C7A Bolt Comment: Qty.: Total: 4.0000 Each(s) 4.0000 Each(s)/Unit Bolt Batch: D34033 23.0 Bushing Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s) Pick: **Qty Part Number** Description 8 D3403-3 Bushing D3405041 24.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description 1 D3405-041 GHW Lug D3405043 25.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description 1 D3405-043 **GHW Lug** 

Dart	Aerospace	Ltd
------	-----------	-----

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		·								
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date:				
			OA·	N/C Close	d·	Date:				

	NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
i			Description of NC	Corrective Action Section B			Verification	A	A	
	DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector	
•		1								



Dart Aerospace L
------------------

Dart Ae	rospace	e Ltd						
W/O:			WC	RK ORDER CHANGES	3			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date 0	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Dord No.	-	DAD #-	FIt O-1					
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes I	No DQA:_	Date: _	
					QA: N/	C Closed: _	Date: _	
NCR:		\	WORK ORD	ER NON-CONFORMAN	CE (NCR	)		·
DATE	STEP	Description of NC Section A	Initial , Chief Eng	Corrective Action Section E Action Description Chief Eng	Sign & Date	Verificati Section (		Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·								
	-							
	1		·				1	

Date: Wednesday, 12/5/2007 12:56:51 PM User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 35741 Job Number: Description: Seq. #: Machine Or Operation: BOLT AN3C40A 32.0 1.0000 Each(s) Comment: Qty.: Total: 1106169 BOLT **BOLT** AN3C41A 33.0 Total: 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit **BOLT** AN3C42A 34.0 Comment: Qty.: 1.0000 Each(s) Total: 4100169 **BOLT** AN3C43A 35.0 Comment: Qty.: 4.0000 Each(s) 4.0000 Each(s)/Unit Total: **BOLT** AN3C46A 36.0 Comment: Qty.: 5.0000 Each(s) M106169 **BOLT** AN960C10L 37.0 Comment: Qty.: 26.0000 Each(s) 26.0000 Each(s)/Unit Total : M107008 washer MS210433 38.0 Comment: Qty.: Total: 13.0000 Each(s) 13.0000 Each(s)/Unit MOTAIL Nut INSPECT 100% KITS FOR COMPLETENESS QC4 39.0 Comment: INSPECT 100% KITS FOR COMPLETENESS

Dart Aerospace	• Ltd
----------------	-------

W/O:  DATE STEP PROCEDURE CHANGE  By Date Qty Approval Chief Eng / Prod Mgr QC  Approval Chief Eng / Prod Mgr QC	
DATE STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr QC	
	roval spector
Part No: PAR #: Fault Category: NCR: Yes No DQA: ₽ Date: △8(G	•
QA: N/C Closed: Date:	
NCR: WORK ORDER NON-CONFORMANCE (NCR)	
DATE STEP Description of NC Corrective Action Section B Verification Approval Approval Approval	roval
	spector

Wednesday, 12/5/2007 12:56:51 PM Date: ·User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 35741 Part Number: D412742013 Job Number: Description: Seq. #: Machine Or Operation: PACKAGING RESOURCE #1 40.0 PACKAGING 1 Identify and pack for shipping as per PPP D412-742-0,13 Location: QC21 41.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHA	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			141.				
Part No	•	PAR #: Fault Category:	NCR: Ye	s No DQ	A:	Date:	1
			QA:	N/C Close	d:	_ Date: _	

NCR:	WORK ORDER NON-CONFORMANCE (NCR)							
DATE STE		Description of NC		Corrective Action Section B	3	Verification	Approval Chief Eng	A
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Approval QC Inspector
						:		

Date:

Tuesday, 29/01/2008 7:55:59 AM

User:

Linda Lacelle

## **Process Sheet**

KJ/JLM

JLM

DD verified

EC

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number **Estimate Number** 

: 35741A : 10756

P.O. Number

This Issue

**Previous Run** 

: 29/01/2008

Prsht Rev. : NC

First Issue

: 05/12/2007

Type

: LANDING GEAR

New Issue

ECN 773 dwg @ rev.D

As per Rev F

ECN 1072

: 35740A

Written By Checked & Approved By

Comment

: Est Rev A 05.10.13

Est Rev B 06.02.13

Est Rev:C 07-05-28 Est Rev:D 07-12-04

by:JLM

**Drawing Name** 

: FLOAT SKID ASSEMBLY

**Part Number** 

: D412742043 : D3391 REV G

**Drawing Number Project Number** 

: N/A

: D **Drawing Revision** Material

**Due Date** 

: 30/12/2007

Qty:

1 Um:

Each

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

If D412-742-043 is a W/O on it's own,

Photocopy bluefile and create labels per PPP D412-742-043 CHG003

2.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

1-Spray inside tube of D3391-021/-023/-025 with LPS-3 as per Dwg D3391

LPS-3 M105005

2-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with saddle holes for proper alignment, using 7/16" "T" Pins.

CAIR Sikaflex-241/-291 105585

Expiry date:

08.07

3-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Coat bolts with LPS "procyon".

Seal all bolts with sikaflex exept ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex.

LPS Procyon MI04251 A/R

A/R

08-07 Expiry date:

4-Remove "T" pins once sikaflex is dry.

5-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser



.03-12

## **Dart Aerospace Ltd**

DuitAc	, oopao	CELU		· ·					
W/O:			WC	RK ORDER CHAN	GES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	):	PAR #:	Fault Cate	gory:	NCR: Yes	s No DO	QA:	Date: _	
					QA:	N/C Close	ed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORM	IANCE (NO	R)			
DATE	STEP	Description of NC			ction B	Verif	Verification Appro		Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat	l <b>ö</b> k   Sec	tion C	Chief Eng	QC Inspector
:									
Ì									****

Tuesday, 29/01/2008 7:55:59 AM Date: User: Linda Lacelle **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 35741A . Job Number: Seq. #: Description: **Machine Or Operation:** 3.0 D3391023 Mid Tube Assembly 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: pick: Batch Part Number Description Qty 835766 D3391-023 Mid Tube Assembly D3391025 Aft Tube Assembly 4.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Qty Part Number Description Batch D3391-025 Aft Tube Assembly 336840 IJĴ WEARSHOE D35641 5.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **WEARSHOE** Batch: 1333243 D35661 GASKET 6.0 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: **GASKET** Batch: 11=7 B37410 1x=7 B37813 D35643 7.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **WEARSHOE** WEARSHOE D35645 8.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) 08-03-17 **WEARSHOE** 37212

## Dart Aerospace Ltd

W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	)	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	<b>A</b> :	Date:	
					QA: N	/C Close	d:	Date:	· · · · · · · · · · · · · · · · · · ·
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NCR	2)			
DATE	E STEP	Description of NC	Description of NC Corrective Action Section B Verificatio				ation	Approval	Approval
DAIL		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	gn &   Section C	on C	Chief Eng	QC Inspector
		-							
						-			

Date: Tuesday, 29/01/2008 7:55:59 AM User: Linda Lacelle **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 35741A Part Number: D412742043 Job Number: Description: Seq. #: **Machine Or Operation:** D35665 GASKET 9.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **GASKET** Batch: (5 AN3C4A 10.0 Comment: Qty.: 24.0000 Each(s)/Unit Total: 24.0000 Each(s) **BOLT** Batch: 1107008 AN3C6A 11.0 Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s) **BOLT** Batch: 12.0 Comment: Qty.: 8.0000 Each(s) 8.0000 Each(s)/Unit Total: **BOLT** Batch: 13.0 AN960C10L Comment: Qty.: 44.0000 Each(s)/Unit Total: 44.0000 Each(s) washer Batch: INSPECT WORK TO CURRENT STEP 14.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #" 15.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-043 Location: PPP Rev:

rospace L	td								
		W	ORK ORDER CHANGES						
STEP	PR	OCEDURE CHA	NGE	Ву	Date	e Qty	Approval Chief Eng / Prod Mgr	Approvai QC Inspector	
=				QA: N	C Closed	: <u> </u>	_ Date: <u> </u>		
	•	WORK ORD	ER NON-CONFORMANO	CE (NCR	)				
TE STEP	Description of NC		Corrective Action Section B		Verifica	ation	Annroval	Approval	
SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sign & Section	Section C		Chief Eng	QC Inspector
	STEP	:PAR #:	STEP PROCEDURE CHA  :PAR #:Fault Cate  WORK ORD  STEP Description of NC Section A Initial	WORK ORDER CHANGES  STEP PROCEDURE CHANGE  :PAR #:Fault Category:N  WORK ORDER NON-CONFORMANO  STEP Description of NC	WORK ORDER CHANGES  STEP PROCEDURE CHANGE By  : PAR #: Fault Category: NCR: Yes (QA: N/  WORK ORDER NON-CONFORMANCE (NCR  WORK ORDER NON-CONFORMANCE (NCR  STEP Description of NC	WORK ORDER CHANGES  STEP PROCEDURE CHANGE By Date  :PAR #:Fault Category:NCR: Yes No DQA QA: N/C Closed  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC Section A Section B Veriffic Section A Section B Sign & Section A Section Part	WORK ORDER CHANGES  STEP PROCEDURE CHANGE By Date Qty  :PAR #:Fault Category:NCR: Yes No DQA: PAR #:	WORK ORDER CHANGES  STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr  :PAR #:Fault Category:NCR: Yes No DQA: Prod Mgr  CARRON Colosed:Date:  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC Section A Section C Section C Section C Section C Chief Eng / Prod Mgr	

Date: User: Tuesday, 29/01/2008 7:55:59 AM

Linda Lacelle

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKID ASSEMBLY

Job Number: 35741A

Part Number: D412742043

. Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

16.0

QC21



Comment: FINAL INSPECTION/W/O RELEASE

FINAL INSPECTION/W/O RELEASE

Job Completion



W 08-03-24

